




Privileged and confidential – prepared in contemplation of mediation  
FOISA exempt

24





CEC02084554\_0002



CEC02084554\_0003



CEC02084554\_0004




Privileged and confidential – prepared in contemplation of mediation  
FOISA exempt





PHOTO 1


Privileged and confidential – prepared in contemplation of mediation  
FOISA exempt



FAULT - MASTIC JOINT BOND BETWEEN PANEL & ROAD  
FAILED.




Photo 3.



FAULTS - ①. DE-BONDING OF MASTIC ROAD/RAIL BOND.  
②. CRACKING OF ASPHALT DUE TO MOVEMENT OF CHAMBER ELEMENT.  
③. CHAMBER ELEMENT MOVING UNDER LOAD.

PHOTO 5.



FAULT. - LOCATED DE-BONDING OF ASPHALT JOINT BETWEEN  
ROAD/PAV. I SUSPECT POOR QUANTITY CONTROL DURING  
INSTALLATION.

PHOTO 7.



FAULT AFTER REMEDIATION - MOVEMENT IN THE OUTER CHAMBER & DEFORMATION