

Parsons Brinckerhoff Edinburgh Tram Project Design Office CityPoint, 1st Floor 65 Haymarket Terrace Edinburgh EH12 5HD United Kingdom 44-(0)131-623-8600 Fax: 44-(0)131-623-8601

Our Ref: ULE90130-03-LET-00199

12th February 2008

tie Limited CityPoint, 1st Floor 65 Haymarket Terrace Edinburgh EH12 5HD

Attention: Graeme Barclay

Dear Graeme

Utilities Design Sub-Section 3A, 3B & 3C

SDS confirm receipt of tie letter ref DEL.MUDFA.6580 dated 15th January 2008.

We are surprised at the content of the letter as it was expected that the confirmation from **tie** was to move forward with the re-design of Section 3 following the relevant Change Order Instruction from **tie**. This was the route formally discussed at previous Utility Progress Meetings. Unfortunately SDS cannot agree to the **tie** letter ref DEL.MUDFA.6580 dated 15th January 2008 and its content, whereby SDS provide additional design materials outside the design programme without additional costs being incurred.

The above referenced tie letter makes it clear that "no additional costs be incurred in either the investigation of existing utility assets or design of diversions".

If no further investigation of existing utility assets is to be carried out, SDS would kindly request clear recognition that **tie** will accept full responsibility for any movement or additions to services by the SUCs (or others) in the geographical sections 3A, 3B, & 3C, since the original SDS IFAs were issued in December 2006. SDS would seek clarification through **tie** that each SUC will provide all relevant C4 Information of utilities moved or amended between 20th December 2006 and the present date.

It is an assumption of SDS that **tie** have sterilised the tramway alignment by the formal issue of Section 42 Notices (Section 59 NRSWA).

SDS respectfully request confirmation that **tie** have issued Section 42 Notices. If so, may we request copies (previously requested) such that we may use these as information material during our future additional design discussions with the relevant SUCs.

As we are to "ensure no additional costs should be incurred in either the investigation of existing utility assets", may we ask tie to procure this information from each SUC prior to any additional re-design commencement by SDS. As we have previously carried out our desktop studies and provided IFA submissions for geographical sections 3A, 3B & 3C, may we formally request the relevant Change Instruction from tie which needs to be accompanied with the following clarifications:

Over a Century of Engineering Excellence In association with Halcrow Corderoy, Ian White Associates Quill Power Communications, SDG Parsons Brinckerhoff Ltd Registered in England and Wales No. 2554514. Registered Office: Amber Court, William Armstrong Drive Newcastle upon Tyne NE4 TYO



- 1. Confirmation that tie have negotiated with each SUC (or others) and have agreed costs for the SUCs (or others) to engage with SDS to provide the "review and technical approval service" required for SDS to complete the design and seek SUC Technical Approval. SDS respectfully remind tie that SDS were informed that tie had not negotiated costs with the SUCs for "review and technical approval" in the geographical sections 3A, 3B & 3C previously. This omission caused a "stalemate situation" in the early months of 2007 and has "frustrated our design completion".
- 2. Confirmation from **tie** that there is recognition by **tie** that additional work will be required to revisit, check and validate current information (post Section 42 Notice confirmation) on all utilities. Upon such confirmation and Instruction to Proceed, SDS will advise the Change Estimate for additional engineering and CAD time (once the scale of the exercise is understood).
- 3. Confirmation that there is recognition of additional work for SDS to re-commence the design and resend drawings and enter dialogue with the SUCs.

Upon the above clarifications, SDS will advise under Change Estimate the relevant additional costs associated with the Instruction to Proceed.

The additional work and re-arrangement of design to suit the MUDFA Utilities Installation Programme (currently V6) will constitute not only additional design time but also prolongation. Please find enclosed a draft from the SDS Utilities Design Programme showing the initial SUC Approval drawings issued and the period of delay on these sections of work to date.

In accordance with Clause 7.5 of the Agreement between **tie** and SDS, we hereby give **tie** notice we now consider by virtue that SDS have been instructed by **tie** to follow the MUDFA Installation Schedule (and rearrange the design deliverable to suit said Schedule), along with the fact that the SUCs had no manpower in place or brief to receive (in December 2006) the initial 3A, 3B and 3C IFA designs, this caused SDS "frustration to our design" and therefore SDS is entitled to and hereby requests an extension of time of 261 Business Days for completion of the utility design work for Section 3A, 3B & 3C.

We look forward to receiving your formal agreement to the Change Instruction for additional work and extension of time and consequential amendments to the Programme and Project Master Programme.

Yours sincerely



Alan Dolan Parsons Brinckerhoff

Encl.

cc. Damian Sharp, tie Steven Bell, tie Steve Reynolds Jason Chandler SDM's David Simmoms, Halcrow Chris Reid, Halcrow

Over a Century of Engineering Excellence

2.2

		RECRIVED
	EDINDURGH TRAM PROJECT DESIGN DIFFICE	
	REFERENCE NO.	
	DISCIPLINE	
Mr Alan Dolan	1)4ilities	Our Ref: DEL.MUDFA.6580,JJ.GB
Edinburgh Tram Project Parsons Brinkerhoff City Point	ACTION COPY HOLGON JS	Date: 15 January 2007
35 Haymarket Terrace	Reid LTH	
EH12 5HD	A.D.	
C	Chris- Pl Div	re written response
Dear Al a n,	So S	can send lother

EDINBURGH TRAM PROJECT - MUDFA Utilities Design Sub-Section 3a/3b/3c

We refer to your recent request for clarification on the status of the design of diversionary works within Section 3, Russell Road to Granton Square. We can confirm that tie expect SDS to continue to progress the design through to IFC standard.

However, SDS should ensure no resources are diverted from any ongoing section under design, such that a delay would occur to the issue of the IFC information. SDS should also be aware that no additional costs should be incurred in either the investigation of existing utility assets or design of diversions.

Please confirm, by return, your programme for the aforementioned design works and named design resources proposed for this section.

Yours sincerely

Graeme Barclay Construction Director – MUDFA

cc Steven Bell	
John Casserly	
lan Clark	
Michael Blake	
Allan Hill	
Phil Douglas	

tie limited

Verity Heuse 19 Haymarket Yards Edinburgh EH12 5BH toi +44(D)131 622 8300 Jax 444(D)131 622 8301 web www.tie.ltd.uic Registered in Scotland No: 230949 at City Chambers. High Stroet, Edinburgh EH1 1YJ

lan	SDS Design Programme	12-Feb-08 10:
Netry ID Activity Idame Originat BL Project Project Finisti Visitanco - BL F M Start Pinish Project Finish Oates 0 1 2 2 11 1 2		April 2007 May 2007 Jone 2007 Jone 2007 A 3 C N O J F M 0:001 1 2 0:1 1 0:0 1 2 0:1 1 0:0 1 2 0:1
Alian associate polician statistic article		
3A and a second products and a second		
A1150 3A laste 0.0d 19 April 7 0.0d A1160 3A Appower 20.0d 19 April 7 17 May-07 0.0d		SA Issue
A 1170 3A Receive Approval 0.0d 17 May-07 12 Feb-08* 183.0d	ادار الإيرانية والمراجع مراجع معرار والمتعار والمتعاد والمعالية المتعاد والمراجع والمراجع	δαιά 3A Receive App
3B Production of the second second		
A1120 3B Issue 0.0d 29-Dec-06 0.0d A1130 3B Approval 20.0d 20-Dec-06 24-Jan-07 0.0d	G 38 Isono	
A1140 38 Receive Approve: 0.03 24-Jan-07 12-Feb-08* 261.0d	¢	د بې که Receive App
CC CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC		
A1090 3C Issue 0.0d 22-Feb-07 0.0d A1100 3C Approval 20.0d 22-Feb-07 23-Mar-67 0.0d	Å 3C bisne ↓	C Antroize
4110 3C Raceive Approval 0.03 23-Mar-07 12 Feb 081 231.00	(le∳ 30 Receive: Appr

Actual Work	Critical Remaining Wo	rk enn	mm Primary Baseline			10 M 1
Commission Remaining Work &	Milestone	Č.	♦ Baseline Milestone	Dave for the		
				Page 1 of 1	11. set and the set of	

CEC01457196_0004